

<b>Document Number</b>		CTN0045	
<b>Title</b>		Yaris Adaptor box Resource allocation	
<b>Approved By</b>		JG	
<b>Revision</b>	<b>Date</b>	<b>Prepared By</b>	<b>Change History</b>
	05/07/2025	CC	Initial release

## Introduction

The Yaris adaptor box #61460 became obsolete when the updated G16E adaptor box #61487 was released.

This document specifies how to configure the resource allocation in the M1 Tune package to account for the G16E Yaris adaptor box internal circuit revisions.

Perform this change when:

- Fitting the updated adaptor box (**61487**) with an existing Package (**for Adaptor box 61460**).

**NOTE:** This document will use the first 5 digits of the serial number for adaptor box reference.

## Adaptor Boxes

Adaptor box #61460.

Obsolete version. From Yaris kit #11412.



Adaptor box #61487.

Updated version. From Yaris kit #11417



## Resource configuration

Resource	Move to	Was
Fuel Pressure Control Pump Output Resource	IGN_LS7	OUT_HB10
Tachometer Output Resource	IGN_LS8	OUT_HB9
Breakout Connector E19 is not connected	E19 is not connected	UDIG6