





NOTE:
 One Bar Map sensors have a green connector.
 Two & three Bar Map sensors have a black connector.



ECU Setup M8			
Sensor Calibration	1 bar	2 bar	3 bar
Display in KPA	12	14	15
Display in PSI	18	20	21
Display in InHg	24	26	27

ECU Setup M4 M4-8			
Sensor Calibration	1 bar	2 bar	3 bar
MAP	100	200	300

ADL Setup

Channel Assignments
 Assign the pressure Channel to the appropriate pin

Sensor Calibration
 Press "Select" and choose correct calibration file for the sensor. For example, Delco 1 Bar MAP.C1P file is for 1 Bar sensor.

NOTE 1:
 + 5V Analog Pins are 18, 28, 44
 0V Analog Pins are 17, 27, 33, 40, 43
 Analog Volt Input Pins are 1, 2, 3, 4, 5, 19, 20, 21, 22, 23, 24, 25, 26, 45, 46, 47, 48, 49, 50